

(18)

(BS)

GOVERNMENT OF ANDHRA PRADESH
ROADS AND BUILDINGS DEPARTMENT

From,
Sri Ch.V.Subbaiah, B.Tech.,
Executive Engineer,
(R&B) Division,
Vijayawada.

To,
Secretary & Correspondent,
Ravindra Bharathi Educational Academy,
Satyanarayanapuram,
Vijayawada.

Letter No. Structural Soundness Certificate/JTO2/2019, Dated: 18-11-2019

Sir,

Sub: - (R&B) Division, Vijayawada – Ravindra Bharathi Educational Academy,
Satyanarayanapuram, Vijayawada-11 – Soundness Certificate – Issued –
Regarding.

Ref: - 1) Lr. No. Nil, Dt. 18-10-2019 of Ravindra Bharathi Educational Academy,
Satyanarayanapuram, Vijayawada.


It is informed that the **RAVINDRA BHARATHI (E.M) HIGH SCHOOL**, constructed in the year **2014** and is located at **D.No. 10-24, M.G. Road, Kanuru Village, Penamaluru Mandal, Krishna District** has inspected by Dy. Executive Engineer (R&B) Buildings sub division, along with Assistant Engineer (R&B) Buildings Section III, Vijayawada and the said School building with the following instructions to the School management

1. No cracks are observed in the building and also painted recently.
2. The width of the staircase steps is 0.30 Mts. as against 0.30 Mts.
3. The width of the staircase flight is 1.35 Mts. as against 1.50 Mts.
4. The height of the hand railing is 0.90 Mts. as against 1.20 Mts.
5. The height of corridor parapet wall is 0.90 Mts. as against 1.20 Mts.
6. The width of the common corridor is 1.84 Mts. as against 2.50 Mts.

Hence, the School management is responsible to take necessary precautions and maintain the requirements.

However, it is Structurally Sound for a period of one year i.e., from 18-11-2019 to 17-11-2020.

Yours faithfully,



Executive Engineer
(R&B) Division, Vijayawada.

For Ravindra Bharathi Educational Academy
V Vamsi koushik
Chairman.

